




## **Best Practice Guide - Compaction & Backfill**

On arrival photograph site and confirm materials noted on job sheet are correct, if not notify your supervisor


Material should be at optimum moisture content, too wet and it will not compact correctly













Repair any damaged apparatus caused by the excavation works. If this is not possible report it to your supervisor



Content Copyright © First Intervention Ltd 2013 all rights reserved dated 24/08/13 Not to be reproduced without the written consent of First Intervention Ltd 01737 780384 Some safety barriers were moved to permit photographing of the works. Acknowledgements: Cappagh Ltd & Enzen Global.



Reinstatement	Fourth Drop Impact Value		
Level	Target Value	Typical Range	Highest Likely
Trench Bed	7	7 ó 8	30
Top of Finefill	10	10 ó 17	-
Top of Backfill	18	17 - 27	-
Top of Subbase	22	24 - 27	-
Top of Roadbase	30	32 - 34	38

Content Copyright © First Intervention Ltd 2013 all rights reserved dated 24/08/13 Not to be reproduced without the written consent of First Intervention Ltd 01737 780384 Some safety barriers were moved to permit photographing of the works. Acknowledgements: Cappagh Ltd & Enzen Global.